

Oil Field Environmental Incident Summary

Incident: 20160720084313

Date/Time of Notice: 07/20/2016 08:43

Responsible Party: EOG RESOURCES, INC.

Well Operator: EOG RESOURCES, INC.

Well Name: AUSTIN 53-3402H

Field Name: PARSHALL

Well File #: 31350

Date Incident: 7/19/2016

Time Incident: 08:30

Facility ID Number:

County: MOUNTRAIL

Twp: 154

Rng: 90

Sec: 34

Qtr: NW NE

Location Description:

Submitted By: Danielle Dupay

Received By:

Contact Person: Danielle Dupay
600 17TH ST STE 1000N
DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	3	Barrels	3	Barrels	3	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 8/31/2016

Clean Up Concluded: 8/8/2016

Risk Evaluation:

N/A

Areal Extent:

Potential Environmental Impacts:

N/A

Action Taken or Planned:

The oil was skimmed off the onsite storm water using oil absorbent pads, the storm water was removed via vac truck and a hydrovac used to removed affected soils. A berm is going to be placed around the tanks and once the tanks are removed further cleanup will be done around tank area.

Wastes Disposal Location: Secure FST

Agencies Involved:

Updates

Date: 7/20/2016 **Status:** Reviewed - Assigned to Other Agency

Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release remained on location according to the report. NDIC retains oversight.